Tech Note 103

215mm Mazda Rotary Clutch Cover Installation

Ref: TN103 Issue Date: Dec 2017 Issue Number: 1

Important Information

In this application, two of the six clutch cover bolts (as pictured below) are shouldered and must be used to correctly centralise the clutch cover to the flywheel.

Failure to use correct bolts or correctly secure the clutch cover to the flywheel may result in serious personal injury or damage to property.



WARNING: Do not use EXEDY products in any situation where engine RPM's may exceed manufacturer's specifications as they can explode unexpectedly causing serious injury or death to vehicle occupants and by standers. The bell housing will not protect vehicle occupants from exploding parts.

BOLTS NOT INCLUDED IN KIT

