## Tech Note 113 Ford Ranger / Mazda BT-50 Clutch Damper

Ref: TN113 Issue Date: April 2020 Issue Number: 1

## **Important Information**

The hydraulic clutch damper located on the firewall (circled in the image below) can perish over time and close inspection of the damper is required at the time of clutch fitment.

Failure to identify or replace faulty clutch damper may result in loss of pedal pressure and/or difficult gear selection.



