Tech Note 062

MR2 Spyder Sequential Transmission Reset

Ref: TN062

Issue date: 25 July 2013

Issue number: 1

After fitting a new clutch to a Toyota MR2 Spyder with a Sequential Manual Transmission (Semi-Auto), it is essential that the gear shift actuator be reset. This resetting will ensure the release mechanism specifically learns the process for clutch engagement / disengagement position and provides optimal clutch operation after installation.

Failure to reset this actuator may result in clutch non release and invalidate the warranty of the clutch kit.

In most cases it is necessary for a Toyota dealer to perform this task.

