

Mitsubishi 3.5 Ltr V6 Magna Plate Fouls on Flywheel.

Ref: TN058

Issue date: May 2013

Issue number: 1

The internal diameter of the flywheel bore/running surface must be checked prior to installation of this clutch kit to ensure the clutch plate has sufficient clearance. If the flywheel bore / running surface measures less than 155mm, EXEDY recommends fitment of clutch kit part number MBK-7684.

Clutch kit MBK-7223 is recommended for fitment to flywheels with bore / running surface greater than 155mm.

Failure to check this bore size may result in clutch release issues due to fouling of the clutch plate rivets on the flywheel (as shown in the picture below).

