## **Tech Note 040**

## Mitsubishi Pajero NM-NP series MBK-7909 & MBK-7909SMF clutch kit installation

Ref: TN040

Issue date: 07 Jun 2010

Issue number: 1

## MBK-7909 & MBK-7909SMF

The clutch plate contained in these clutch kits is of a wide angle damper (WAD) design and requires the flywheel bore to be 170 +/- 0.5 mm for clearance.

Should you have any queries regarding this Tech Note, please contact your local Exedy distributor for further assistance.

