

# BMW Release Bearing to Clutch Fork Installation

Ref: TN088

Issue date: Dec 2015

Issue number: 1

## CAUTION



In this application it is possible to incorrectly fit the clutch release bearing to the clutch fork.

The clutch release bearing must be installed with the shorter (28.5mm) bearing pivot surfaces contacting the clutch fork.

Failure to correctly install the release bearing may potentially result in de-adjustment of the self-adjusting clutch assembly and unsatisfactory clutch operation.