Tech Note 094 Japanese Trucks with American Drivetrain

Ref: TN094 Issue Date: Oct 2016 Issue Number: 1

When replacing a manual adjust clutch in a Japanese truck that does not already have a clutch brake fitted, please install the enclosed friction washer. This friction washer assumes the thickness of a standard 0.380" clutch brake and ensures the Autoset clutch is operating in the correct position following installation.



