Tech Note 109

Correct DMF Crankshaft Dowel Positioning

Ref: TN109 Issue date: January 2020 Issue number: 1

Important Information!

Please note, it is possible to incorrectly locate this Dual Mass Flywheel on the engine's crankshaft. To ensure correct positioning of the flywheel during installation, the locating dowel of the crankshaft must be properly aligned with the dowel hole located on the engine side of the Dual Mass Flywheel (shown in figure 1 below).




Figure 1

