
Tech Note 036

Holden Commodore VT-VZ V8 Including Utes – CSC identification

Ref: TN036 Issue date: 22 Sep 2009 Issue number: 1

V8 Holden Commodore CSC identification issue: -

Two different designs of Concentric Slave Cylinder (CSC) exist for Holden Commodore models fitted with both Gen III and Gen IV V8 engines.



Should you encounter a vehicle with an incorrect delivery line fitting, both line fittings are interchangeable & can be removed by removing the roll pin using a suitable pin punch.

Take care to not damage the square section seal when replacing the desired fitting.

