Tech Note 050

Ford XR8 FMK-7893SMFHD Clutch Kit Fitment

Ref: TN050 Issue date: 15 Aug 2011 Issue number: 1

Ford XR8 FMK-7893SMFHD Clutch Kit

To allow access to the bleed nipple and clearance for the delivery line, the bell housing should be relieved as shown in the images below.

This is necessary as the ten (10) mm spacer between the CSC and transmission is required to re-position the CSC.





